






NEW PRODUCTS NP-269

Illustration	Ref. No.	Application	On Sale
<p>IVR-995 12V</p>  <p>200PCS./CARTON CARTON SIZE: 57×34×29cm(0.0562m³) G/W: 7.0kg</p>	<p>31150-5R0-004</p> <p>ALTERNATOR 12V 31100-5R0-004 31100-5R7-A01 31100-5R7-A02 (A005TZ0091)</p>	<p>HONDA FIT(JAZZ)</p> <p>GK3, GK4 (L13) GK5 (L15)</p> <p>'13~ '13~</p> 	<p>OCT.'19</p>



New-Era No.	Parts No.	Car Maker	Car Model	Model No.	Engine Model	Model Year	On Sale
<p>MIC-H3108</p>  <p>20PCS./CARTON CARTON SIZE: 64×27×21cm(0.03629m³) G/W: 19.0kg</p>	<p>30520-55A-005</p>	<p>HONDA</p>	<p>JAZZ CITY HR-V BRIO BR-V MOBILIO</p>			<p>'14~ '14~ '15~</p>	<p>OCT.'19</p>

<http://www.newera.co.jp/>


ADDITIONAL APPLICATION

Illustration	Ref. No.	Application
<p>IVR-5019 12V</p> 	<p>(126600-3360) (126600-3390)</p> <p>ALTERNATOR 12V 27060-0A110 27060-0A120 27060-0A130 27060-0A140 27060-0H110 27060-0T130 27060-0V010 27060-0C030 27060-0V060 27060-0P240 27060-0M040</p>	<p>TOYOTA FORTUNER HILANDER HILUX INNOVA KIJANG INNOVA VIOS / YARIS</p> <p>'08~'11 '07~'13 '08~'11 '11 '08~'11 '07~'13</p>  <p style="color: red; text-align: center;">Installed together with D-900.</p>

CORRECTION (2018 IGNITION COIL CATALOGUE)

<p>MIC-2028</p> 	<p>YF09-18-10X 1E05-18-100B 1E04-18-10X C201-18-100 1F20-18-100 L813-18-100 988F-12029-AB 988F-12029-AC 988F-12257-AB 988F-12024-AB 1S7G-12029-AB 1S7G-12029-AC XS82-12-29-AA</p>	<p>MAZDA</p>	<p>TRIBUTE MAZDA 121 MAZDA 2</p>	<p>DW DY</p>	<p>(YF) (FXJA,FYJA) (1.3L) (1.8L,2.0L) (ED) (J4B,J6A) (J4B,J6A)</p>	<p>'00~'08 '96~'03 '03~'05 '98~ '98~ '98~'01 '96~'98 '98~'99 '98~ '97~'02</p>
		<p>VOLVO</p>	<p>S40 V50</p>			<p>'05~ '05~</p>

THE MAZDA(FORD) "L813-18-100" is replaced to "MIC-2040".

<p>MIC-2040</p> 	<p>L813-18-100 0E5G-12029-A</p>	<p>MAZDA FORD</p>
--	-------------------------------------	--