







**NEW PRODUCTS NP-288**

New-Era No.	Ref. No.	Car Maker	Car Model	Engine Model	Model Year
<b>NCS-N004</b> 	23731-AL60A 23731-AL60C	<b>NISSAN</b>	350Z ALTIMA MAXIMA MURANO PATHFINDER QUEST	VQ35DE VQ35DE VQ35DE VQ35DE VQ35DE VQ35DE	'03~'06 '02~'06 '02~'08 '03~'08 '03~'04 '04~'06
		<b>INFINITI</b>	F35 GX35 I35 M35	VQ35DE VQ35DE VQ35DE VQ35DE	'03~'08 '03~'07 '02~'04 '06~'08
<b>NCS-N007</b> 	23731-31U10 23731-31U11	<b>NISSAN</b>	MAXIMA  PATHFINDER CEDRIC	VQ20DE VQ30DE VQ35DE VQ35DE VQ30DE	'00~'03 '95~'01 '02 '01~'02 '92~'95
		<b>INFINITI</b>	I30 QX4	VQ30DE VQ20DE, VQ30DE VQ35DE	'96~'01 '95~'00 '01~'03
<b>NCS-N008</b> 	23731-ED02A 23731-ED02B 23731-ED02C	<b>NISSAN</b>	CUBE JUKE MICRA NOTE NV200 QASHQAI TIIDA	HR16DE HR16DE HR16DE HR16DE, HR12DE HR16DE HR16DE HR16DE	'10 '18 '05~'10 '06~'13 '10 '07~'13 '07~'12
		<b>NISSAN</b>	ALMERA CABSTAR MURANO NAVARA NT400 PATHFINDER PRIMERA X-TRAIL	YD22DDT (i) YD25DDTi YD25DDTi YD25DDTi YDE5K3KD-5LD YD25DDTi YD22DDT YD22DDT (i)	'03~'06 '06~'14 '10~'14 '02~'10 '14 '05 '02~'07 '01~'13
<b>NCS-N009</b> 	23731-AW410 23731-EC00A	<b>NISSAN</b>	ALMERA CABSTAR MURANO NAVARA NT400 PATHFINDER PRIMERA X-TRAIL	YD22DDT (i) YD25DDTi YD25DDTi YD25DDTi YDE5K3KD-5LD YD25DDTi YD22DDT YD22DDT (i)	'03~'06 '06~'14 '10~'14 '02~'10 '14 '05 '02~'07 '01~'13
		<b>NISSAN</b>	ALMERA CABSTAR MURANO NAVARA NT400 PATHFINDER PRIMERA X-TRAIL	YD22DDT (i) YD25DDTi YD25DDTi YD25DDTi YDE5K3KD-5LD YD25DDTi YD22DDT YD22DDT (i)	'03~'06 '06~'14 '10~'14 '02~'10 '14 '05 '02~'07 '01~'13
<b>NCS-T008</b> 	90919-05045 90919-05081 90919-05087	<b>TOYOTA</b>	AURIS PRIUS WILL CYPHA YARIS VERSO YARIS/VITZ	1NZ-FE 1NZ-FXE 1NZ-FE, 2NZ-FE 1NZ-FE, 2NZ-FE 1NZ-FE 2NZ-FE 1NZ-FXE	'06~'12 '03~'09 '01~'05 '99~'05 '01~'05 '99~'05 '12
		<b>TOYOTA</b>	AURIS PRIUS WILL CYPHA YARIS VERSO YARIS/VITZ	1NZ-FE 1NZ-FXE 1NZ-FE, 2NZ-FE 1NZ-FE, 2NZ-FE 1NZ-FE 2NZ-FE 1NZ-FXE	'06~'12 '03~'09 '01~'05 '99~'05 '01~'05 '99~'05 '12
<b>NCS-M004</b> 	MD327107	<b>MITSUBISHI</b>	LANCER MK LANCER MK IV LANCER SALOON	4G15 4G15 4G63 TURBO	'83~'90 '88~'92 '98~'01 '04 '06
		<b>MITSUBISHI</b>	LANCER MK LANCER MK IV LANCER SALOON	4G15 4G15 4G63 TURBO	'83~'90 '88~'92 '98~'01 '04 '06
<b>NCS-M005</b> 	MR985041 J5T3147	<b>MITSUBISHI</b>	COLT COLT VI LANCER VII	4A91 3A91, 4A91 4A91	'06~'09 '04~'12 '08, '10
		<b>SMART</b>	FORFOUR	M 134.910/911 M 135.950	'04~'06 '04~'06

<http://www.newera.co.jp/>

**Follow Us!!** 



**New-Era Co., Ltd.**



# NEW PRODUCTS NP-289

New-Era No.	Ref. No.	Car Maker	Car Model	Engine Model	Model Year
<b>NCS-Z001</b> 	FSD-18-221 ZL01-18-221 ZL01-18-221A J005T27072	<b>MAZDA</b>	MAZDA 323 DEMIO MX-5 / MIATA	FP55,ZL05/06,RF3F,RF1G B3ME, B5E	'98~'04 '98~'03 '98~'05
		<b>CAM SHAFT POSITION SENSOR</b>			
<b>NCS-H001</b> 	37840-RJH-006 37840-PLC-006 37840-PLC-000	<b>HONDA</b>	CIVIC VII COUPE FR-V STREAM	D17A1/2/5/6/7/8 D17A2 D17A2	'01~'05 '04 '01
		<b>ACURA</b>	EL	D17A2	'04~'05
<b>CAM SHAFT POSITION SENSOR</b>					
<b>NCS-S001</b> 	33220-70E00 J5T10771	<b>SUZUKI</b>	BALENO SWIFT VITARA X-90 WAGON R	G16B G13A/B G16B G16B G13BB	'95~'02 '85~'01 '98~'02 '95~'97 '06~'21
		<b>SUBARU</b>	JUSTY	EF13 G13BB	'95~'10 '01~'13
<b>CRANK SHAFT POSITION SENSOR</b>					
<b>NCS-X008</b> 	0K30A-18891	<b>KIA</b>	RIO SEDONA	A3E, A5D K5, KV6	'01~'05 '01~'06
		<b>CRANK SHAFT POSITION SENSOR</b>			
<b>NCS-X009</b> 	39310-38070	<b>HYUNDAI</b>	SANTA FE SONATA	G4JS-G, G4BP, G4JP G4JS	'01~'06 '99~'05
		<b>KIA</b>	OPTIMA SORENTO	GS4JS GS4JS	'01~'06 '02~
<b>CRANK SHAFT POSITION SENSOR</b>					
<b>NCS-X010</b> 	39318-39800	<b>KIA</b>	SORENTO	G6AU G6CU	'03~'06 '02~
		<b>CAM SHAFT POSITION SENSOR</b>			
<b>NCS-X011</b> 	96325867	<b>CHEVROLET</b>	AVEO SPARK (MATIZ)	F12S3, LY4 F8CV, B10S, LA2	'06~'07 '05
		<b>DAEWOO</b>	KALOS MATIZ	B12S1, F12S3 F8CV	'03 '98
<b>CAM SHAFT POSITION SENSOR</b>					
<b>NCS-X012</b> 	96325868	<b>CHEVROLET</b>	AVEO SPARK (MATIZ) NUBIRA	F12S3, LY4, F14D3, L14 F8CV, B10S1, LA2 F14D3	'06~'07 '05 '06
		<b>DAEWOO</b>	KALOS LACETTI MATIZ TICO	B12S1, F12S3, F14D3 F14D3 F8CV F8CV	'03 '04 '98 '96~'00
<b>CRANK SHAFT POSITION SENSOR</b>					
<b>NCS-X013</b> 	39350-2B000 39350-2B010 39350-2B030	<b>HYUNDAI</b>	I10 I20 I30 IX20 VELOSTER	G3LA, G4LA G4FA, G4FC, G4LA G4FA, G4FC, G4FD G4FA, G4FC G4FD	'08~'13 '08~'15 '07~'12 '10 '11
		<b>KIA</b>	CARENS CEE'D CERATO PICANTO RIO SOUL SPORTAGE	G4FC / G4FD G4FC, G4FD G4FC G3LA, G4LA G4LA G4FC G4FD	'09~'10/'13 '06~'12 '06 '11 '11 '11 '11
<b>CAM SHAFT POSITION SENSOR</b>					
<b>NCS-X014</b> 	39350-02710 39350-02800	<b>HYUNDAI</b>	AMICA GETZ I10	G4HD, G4HG G4HG G4HG	'03~'10 '05~'09 '07~'13
		<b>KIA</b>	PICANTO	G4HE, G4HG	'04
<b>CAM SHAFT POSITION SENSOR</b>					