

New-Era Co., Ltd.

1-7-21, Nakagawa-higashi, Ikuno-ku, Osaka, Japan

Phone: 81-6-6754-8585 FAX: 81-6-6754-3030

2022.4.1

| Series | Product | New-Era No. | Application |
|----------------------|-------------------|----------------------|--|
| AVR | Voltage Regulator | AVR-714 | NISSAN |
| | Voltage Regulator | AVR-551J | TOYOTA / DAIHATSU / SUZUKI |
| | Voltage Regulator | AVR-554J | TOYOTA |
| | Voltage Regulator | AVR-555 | TOYOTA |
| | Voltage Regulator | AVR-557 | ISUZU |
| IVR | IC Type Regulator | DIVR-860600 | NISSAN |
| | IC Type Regulator | IVR-5026 | HONDA |
| | IC Type Regulator | IVR-604 | KOMATSU / NISSAN |
| | IC Type Regulator | IVR-803 | ISUZU |
| | IC Type Regulator | IVR-804 | ISUZU |
| | IC Type Regulator | IVR-959 | NISSAN |
| | IC Type Regulator | IVR-961 | MITSUBISHI |
| | IC Type Regulator | IVR-983 | NISSAN |
| D | Rectifier | D-028 | MAZDA |
| | Rectifier | D-029 | SUZUKI |
| | Rectifier | D-030 | MAZDA |
| | Rectifier | D-034 | MAZDA |
| | Rectifier | D-035 | NISSAN |
| | Rectifier | D-039 | MAZDA |
| | Rectifier | D-602 | NISSAN |
| | Rectifier | D-603 | NISSAN |
| | Rectifier | D-901 | HONDA / HYUNDAI |
| | Rectifier | D-902 | TOYOTA / HONDA |
| FLS | Flasher Relay | FLS-101 | IUZU |
| | Flasher Relay | FLS-102 | MITSUBISHI FUSO / HINO |
| | Flasher Relay | FLS-103 | MITSUBISHI |
| | Flasher Relay | FLS-104 | ISUZU |
| | Flasher Relay | FLS-105 | ISUZU |
| | Flasher Relay | FLS-106 | ISUZU |
| | Flasher Relay | FLS-107 | MITSUBISHI |
| | Flasher Relay | FLS-108 | MITSUBISHI |
| | Flasher Relay | FLS-109 | TOYOTA / ISUZU |
| | SS | Starter Solenoid 24V | SS-1890 |
| Starter Solenoid 24V | | SS-2501 | ISUZU |
| NPR | Mini Relay | NPR-301 | MB141967 |
| | Mini Relay | NPR-502 | 90987-02016 / 90987-02025 156700-1570 / 156700-2540 |
| | Mini Relay | NPR-504 | 90987-02006 / 90987-02007 056700-7030 |
| | Mini Relay | NPR-601 | 8-94235-627-0 |
| | Mini Relay | NPR-602 | 8-94218-497-0 |
| | Mini Relay | NPR-604 | 8-94112-912-0 |

✕Discontinued at the end of June, 2022!!